



STATION
BUS
CLASS 2

LVOS-0-10-
PWM-DIN

1 2 3 4
IR SENS GND GND
CONTACT INPUTS

+12V +12V
50mA
MAX

GND ON GND OFF
OVERRIDE

SERIAL NUMBER

STATION
BUS
CLASS 2

VANTAGE

1 2 3 4 5 6 7 8

RED = 0-10
GREEN = PWM

LOW VOLTAGE OUTPUT STATION-0-10-PWM-DIN

STATUS

CE

DC IN GND

13.8-36
VDC

1 2 3 4 5 6 7 8
OUT GND OUT GND OUT GND OUT GND OUT GND OUT GND OUT GND

0-10: 10V@100mA
PWM: 12V@100mA

CE

DC IN GND

ADC
13.8-36

1 2 3 4 5 6 7 8
TWO GND TWO GND TWO GND TWO GND TWO GND TWO GND TWO GND

LOW: 15A@100V
0-10: 10A@100V